









LEGEND

-  Indicates approximate location of monitoring well installed by D-Max in January-March 2001
-  Indicates approximate location of monitoring well installed by D-Max in February 2000
-  Indicates approximate location of test boring
-  Indicates approximate location of monitoring well by Arco

-  Indicates approximate location of tank pit soil sample
-  Indicates approximate location of removed pipes
-  Fence



LYTTON STREET

MONITORING WELL LOCATIONS
HAWLEY AUTO BODY AND PAINT
2902 LYTTON STREET, SAN DIEGO, CA

FN: WELL	DB: CM	CHECKED BY:	DATE: 8-17-04
PROJECT NO: 200329H-1			FIGURE NO: 1